Inspection Report

Provided by: Michael Helms



H3 Inspection and Services

Inspector: Michael Helms

Michael Helms 256-975-8859 H3inspectionandservices@gmail.com

www.H3inspection.com Alabama License: HI4457

Property Address

1234 Happy Ave Huntsville Al. 35763



Table Of Contents:

Section name:	Page number

Report Information	
Report Summary Page	5
Grounds	88
Exterior	
Roofing	
Heating - Air	19
Electrical	20
Plumbing	23
Downstairs study/bedroom	25
Dining room	27
Living Room	28
Primary Bedroom	30
Upstairs Bedroom 1 (front of house)	34
Upstairs Bedroom 2 (back of house)	36
Bonus Room 1 (upstairs Bedroom 3)	
Bonus Room 2 (back of house with door leading to porch)	39
Kitchen	40
Primary Bathroom	44
Downstairs Bathroom	47
Upstairs Bathroom	49
Garage - Laundry	51
Foundation - Crawl Space	53

Report Information

Client Information

Client Name Client: Mr. And Mrs. Smith

Client Phone 256-975-5555

Property Information

Approximate Year Built 2010

Approximate Square Footage 3600 Square Feet

Number of Bedroom 4/5

Number of Bath 3. Full

Direction House Faces West.

Inspection Information

Inspection Date

06/2020

Inspection Time 12:00 pm

Weather Conditions Dry.

Outside Temperature 96

Price for Inspection \$400.

WITHIN THE SCOPE OF THE INSPECTION

The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See Standards of Practice for a detailed description of the scope of inspection.

Exterior:Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

Interior:Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible)(as to evidence of water damage and general condition.) - The scope of the inspection is limited to the description and the general condition of the above systems.

OUTSIDE THE SCOPE OF THE INSPECTION

-Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection. -The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;

- Building code or zoning ordinance violations - Thermostatic or time clock controls or Low Voltage wiring systems - Geological stability or soils conditions - Water softener or water purifier systems or solar heating systems - Structural stability or engineering analysis - Saunas, steam baths, or fixtures and equipment - Building value appraisal or cost estimates - Pools or spa bodies or sprinkler systems and underground piping - Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters - Furnace heat exchanger, freestanding appliances, security alarms or personal property - Specific components noted as being excluded on the individual system inspection form - Adequacy or efficiency of any system or component - Prediction of life expectancy of any item. - The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

CONFIDENTIAL REPORT

- The written report to be prepared by the Inspector shall be considered the final and exclusive findings of the Inspector/Inspection Company regarding the home inspection at the Inspection Address. The inspection report to be prepared for the Client is solely and exclusively for the Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person with the exception of the seller and/or the real estate agents directly involved in this transaction. Client(s) or the inspector may distribute copies of the inspection report to the seller and real estate agents directly involved in this transaction, but neither the seller nor the real estate agent are intended beneficiaries of this Agreement or the inspection report. Client agrees to indemnify, defend, and hold the Inspector/inspection Company harmless from any third party claims arising out of the Client's or Inspectors distribution of the inspection report.

DISPUTES

- Client understands and agrees that the Inspector/Inspection Company is not an insurer, that the price paid for the subject inspection and report is based solely on the service provided. Client also agrees that any claim of failure in the accuracy of the report shall be reported to the Inspector/Inspection Company within five business days of discovery and that failure to notify the inspector within that time period shall constitute a waiver of any and all claims. The Inspector/Inspection Company shall have five business days to respond to the claim. If the Inspector/Inspection Company fails to satisfy the claim, liability shall be limited to a refund of the price paid for the Inspection and Report.

Definition of conditions:

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

MI = The item, component, or system while perhaps functioning as intended is in need of minor repair, service or maintenance; is showing signs of wear or deterioration that could result in an adverse condition at some point in the future. Items falling into this category can frequently be addressed by a homeowner or general contractor and are considered to be routine homeowner maintenance.

R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.

S = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

Report Summary Page				
This is only a summary of the inspection report and is not a complete list of discrepancies.				
Section	Condition#	Comment		
		Grounds		
Driveway Conditions	1.2	Common cracks and settlement were observed. The driveway has some surface erosion and minor deterioration.		
Sidewalk Conditions	1.3	Common cracks of up to ¼ inch were observed. The surface was raised or settled. This may cause tripping hazards. These should be repaired for safety.		
		Exterior		
Front Entrance Conditions	2.1	Minor slab settlement was observed. Some repair may be warranted. The front porch steps foundation has settled. You can see railing has slightly come loose from house and slight separation of stairs from house foundation. It is suggested that a "Licensed General Contractor" be contacted for further evaluation and repair.		
Exterior Wall Conditions	2.3	Moisture damage and possible evidence of water penetration were observed above back covered porch wall. Due to conditions observed, hidden damage may exist in areas not visible or readily accessible.		
Window Conditions	2.4	The thermal pane window(s) at appear to have lost its / their thermal seal. Moisture, fogging, and hazing are common signs of this condition. While mostly cosmetic, this condition is generally not repairable. Correction would require replacement of the window(s) or window pane(s).		
Exterior Door Conditions	2.5	All doors appear serviceable. There were a few issues observed. 1. "Man door" to garage has small area of rotted wood at bottom of th frame(casing) the "man" door was also difficult to operate deadbolt. 2. Back door to sun room trim has damage toward the bottom of the trim 3. Back door from sun room into house has damage to trim. Pet relate scratching / damage was observed at door(s).		
	Roofing			
Flashing Conditions	3.2	The exposed flashings appeared to be in serviceable condition at the time of inspection. Separations were observed in the exposed flashing at the roof to wall connections. It is suggested that a "Licensed Roofing Contractor" be contacted for further evaluation and repair.		
Gutter & Downspout Conditions	3.3	The gutters at the rear corner of the sun porch were filled with leaves and debris at the time of the inspection. Suggest cleaning and removal of debris on a regular basis. This condition can cause water penetration at the eave area. Recommend gutter downspouts be extended and routed away from the building for proper drainage. Water seepage into crawl spaces, basements and under foundations can be caused by inadequate removal of rainwater from the perimeter of the house.		

Report Summary Page					
Attic Conditions	3.4	Evidence of rodents () were observed. While this observation may exist now, the occurrence may have been some time ago. Client should contact a pest control company for further evaluation.			
	Heating - Air				
Unit Conditions	4.1	Heat was off for the season. Heat within the unit could not be tested.			
		Primary Bedroom			
Ceiling Conditions	10.2	There were stains at primary bedroom closet. The stain was dry at time of inspection. The inspector was unable to determine if the leak was active at the time of the inspectuon. Further evaluation by a qualified contractor is recommended. Please refer to limitations of inspection regarding mold / moisture related conditions.			
Interior Window Conditions	10.5	The thermal pane window(s) at front side of house appear to have lot its / their thermal seal. Moisture, fogging, and hazing are common signs of this condition. While mostly cosmetic, this condition is generally not repairable. Correction would require replacement of the window(s) or window pane(s).			
Interior Door Conditions	10.6	Pet related scratching / damage was observed at doors.			
	U	Ipstairs Bedroom 1 (front of house)			
Interior Window Conditions	11.5	Some of the window screens were missing or not installed at time of inspection.			
	L	Ipstairs Bedroom 2 (back of house)			
Floor Conditions	12.3	The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. Some staining was found on the carpets.			
	B	Sonus Room 1 (upstairs Bedroom 3)			
Floor Conditions	13.3	The carpet has stains in a couple areas			
	1	Kitchen			
Floor Conditions	15.3	The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. There was one section of hardwood in the breakfast area that is slightly warped			
Kitchen Window Conditions	15.5	Cracked glass pane(s) were observed at breakfast room top left window. There is a small chip in the window. Recommend repair as needed.			
	Primary Bathroom				


Report Summary Page			
Shower - Tub Conditions	16.12	The sunken tub has a leak when you fill the tub up to the top jet intal and motor for "whirlpool" does not work.	
		the steam shower does not produce steam. Steam generator does not appear to work. In addition the steam shower has a leak as evident when inspecting the subfloor in the crawlspace.	
Downstairs Bathroom			
Electrical Conditions	17.6	GFIC (Ground Fault Interrupter Circuit) receptacle circuit (a safety device for outlets near water) recommended next to sink.	
Garage - Laundry			
Door Conditions	19.7	Moisture related damage was observed. Recommend further evaluation and repair as needed by a qualified / licensed contractor.	
Foundation - Crawl Space			
Flooring Support Conditions	20.2	The steam shower in the master bathroom appears to have a leak. The subfloor is wet. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.	

1 Grounds

Grading

Grading Slope

The site grading slope is steep in some area and moderately sloped in others



1.1) Grading Conditions



Grading of the soil near the foundation appears to be in serviceable condition.

Driveways - Sidewalks - Walkways

Driveway Material

Asphalt.

1.2) Driveway Conditions



Common cracks and settlement were observed. The driveway has some surface erosion and minor deterioration.



Sidewalk Material

Concrete.

1.3) Sidewalk Conditions



Common cracks of up to $\frac{1}{4}$ inch were observed. The surface was raised or settled. This may cause tripping hazards. These should be repaired for safety.



Retaining Wall

Retaining Wall Material

Block.

1.4) Retaining Wall Conditions



The visible and accessible portions of the retaining walls appeared to be in serviceable condition at the time of the inspection.

2 Exterior

Front - Back Entrance

Front Entrance Type

Covered Porch.

2.1) Front Entrance Conditions



Minor slab settlement was observed. Some repair may be warranted. The front porch steps foundation has settled. You can see railing has slightly come loose from house and slight separation of stairs from house foundation. It is suggested that a "Licensed General Contractor" be contacted for further evaluation and repair.



Brick step foundation has settled



Railing slight separation from brick

Back Entrance Type

Covered Patio.

2.2) Back Entrance Conditions



The visible portions of the patio appeared to be in serviceable condition at the time of the inspection.

Exterior Walls

Structure Type

Concrete Block. Brick.


Exterior Wall Covering

The visible and accessible areas of the exterior siding material are brick. The visible and accessible areas of the exterior siding material are vinyl.

2.3) Exterior Wall Conditions



Moisture damage and possible evidence of water penetration were observed above back covered porch wall. Due to conditions observed, hidden damage may exist in areas not visible or readily accessible.





Some discoloration on siding





Exterior Windows - Doors

Window Type

Window Material

Double Hung.

Vinyl.

2.4) Window Conditions



The thermal pane window(s) at appear to have lost its / their thermal seal. Moisture, fogging, and hazing are common signs of this condition. While mostly cosmetic, this condition is generally not repairable. Correction would require replacement of the window(s) or window pane(s).



Themal seal broken



Thermal seal broken

2.5) Exterior Door Conditions



All doors appear serviceable. There were a few issues observed.

- 1. "Man door" to garage has small area of rotted wood at bottom of the frame(casing) the "man" door was also difficult to operate deadbolt.
- 2. Back door to sun room trim has damage toward the bottom of the trim
- 3. Back door from sun room into house has damage to trim. Pet related scratching / damage was observed at door(s).



1. Rotted trim





2. Trim damage

Exterior Water Faucet(s)

Faucet Location

South side of home.

2.6) Faucet Conditions



The hose faucets appeared to be in serviceable condition at the time of the inspection. These should be drained prior to freezing temperatures.

Chimney

2.7) Chimney Conditions



The visible and accessible portions of the chimney(s) appeared to be in serviceable condition at the time of the inspection. Due to height and / or conditions observed, chimney was viewed from the ground only using high-powered binoculars.

3 Roofing

Roof Covering

Method of Inspection

The roof was inspected by observing from a ladder placed at the edge of the roof. The roof was inspected by viewing with high power binoculars. The roof was inspected by walking the safe and accessible areas.

Roof Style

Combination of gable and hip.



Roof Covering Material

Asphalt composition shingles.

Number of Layers

One.

3.1) Roof Covering Condition



Minor sagging or depressions were observed to the roof sheathing and / or framing support. The general condition of the roof shingles shows signs of weathering and aging. Although replacement does not appear to be necessary at this time, we recommend maintenance be performed on a regular basis with annual inspection by a qualified roofing contractor.

3.2) Flashing Conditions



The exposed flashings appeared to be in serviceable condition at the time of inspection. Separations were observed in the exposed flashing at the roof to wall connections. It is suggested that a "Licensed Roofing Contractor" be contacted for further evaluation and repair.

3.3) Gutter & Downspout Conditions



The gutters at the rear corner of the sun porch were filled with leaves and debris at the time of the inspection. Suggest cleaning and removal of debris on a regular basis. This condition can cause water penetration at the eave area. Recommend gutter downspouts be extended and routed away from the building for proper drainage. Water seepage into crawl spaces, basements and under foundations can be caused by inadequate removal of rainwater from the perimeter of the house.



Clogged and evidence of past leaks



Extend 4-6 feet away from house



Extend 4-6 feet away from house



Slight damage to gutter near garage door



Extend gutter 4-6 feet away from house

Attic Area

Attic Access Guest Bedroom.

Method of Inspection Entered attic area.

Roof Frame Type The roof framing is constructed with rafter framing.

3.4) Attic Conditions

Evidence of rodents () were observed. While this observation may exist now, the occurrence may have been some time ago. Client should contact a pest control company for further evaluation.

Attic Ventilation Type No Vents Present. Spray foam

3.5) Attic Ventilation Conditions

Appears Serviceable.

Attic Insulation Type Spray Foam.

3.6) Attic Insulation Conditions AS

Appears Serviceable.

4 Heating - Air

Heating

Location of Unit Attic.

Heating Type Forced Air.

Energy Source Electric.

Approximate BTU Rating The BTU's were not available.

4.1) Unit Conditions

Heat was off for the season. Heat within the unit could not be tested.

Distribution Type The visible areas of the heat distribution system is

ductwork with registers.

4.2) Distribution Conditions

The visible and accessible areas of the distribution system appeared to be in serviceable condition at the time of inspection.

4.3) Ventilation Conditions

The visible and accessible portion of the venting flue appeared to be in serviceable condition at the time of the inspection.

4.4) Thermostat Condition AS

The normal operating controls appeared to be serviceable at the time of the inspection.

Air Condition - Cooling

Type of Cooling System Split system.

AC Unit Power 240V.

4.5) AC Unit Conditions AS

An air handler is present in the attic. Air handler general cleaning and servicing is recommended on a yearly basis. Tracing of condensate piping and termination points is not performed as part of this inspection. Condition of the air handler unit base pan can only be determined by removal of factory installed insulation and or factory panels which is not performed as part of this inspection.

5 Electrical

Service Drop - Weatherhead

Electrical Service Type

The electrical service is underground.



Electrical Service Material

Copper.

Number of Conductors

Appears Serviceable. Three.

5.1) Electrical Service Conditions



The main service entry appeared to be in serviceable condition at the time of inspection.

Main Electrical Panel

Main Disconnect Location

At Main Panel.

Electric Panel Location

The main electric panel is located at the garage.



Panel Amperage Rating

The electrical capacity of main breaker was listed / labeled as 200 amps.

Circuit Protection Type

Breakers.



5.2) Wiring Methods

AS

Plastic insulated (romex) type wire is present.



5.3) Electrical Panel Conditions



Appears Serviceable.

Electrical Subpanel

Subpanel Location

A sub panel is located at the garage.

5.4) Subpanel Conditions



The sub panel appeared to be in serviceable condition at the time of inspection.

6 Plumbing

Water Main Line

Main Shutoff Location The main valve is located at the crawl space.

Main Line Material The visible material of the main line / pipe appears to be

copper.

6.1) Main Line & Valve Conditions



The visible portion of the main pipe and valve appeared to be in serviceable condition at the time of the inspection.

Water Supply Lines

Supply Line Material The visible material used for the supply lines is copper.

6.2) Supply Line Conditions

The visible portions of the supply lines appeared to be in serviceable condition at the time of inspection. All of the supply lines were not fully visible or accessible at the time of the inspection.

Drain - Waste Lines

Drain Line Material The visible portions of the waste lines are cast iron.

6.3) Drain Line Conditions AS

The visible portions of the waste lines appeared to be in serviceable condition at the time of inspection. All of the waste lines were not fully visible or accessible at the time of the inspection.

Water Heater(s)

Water Heater Type Natural Gas.

Water Heater Location Outside garage



Tankless hot water heater

Water Heater Capacity

Non applicable. Tankless hot water heater

6.4) Water Heater Conditions



The water heater was operable at the time of inspection. This does not however guarantee future performance, operation, or condition.

7 Downstairs study/bedroom

Walls - Ceilings - Floors

7.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



Downstairs study/bedroom

7.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

7.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

7.4) Heat Source Conditions



58.1 degrees

Windows - Doors

7.5) Interior Window Conditions



Appears Serviceable.

AS = Appears Serviceable MI = Maintena	ice Issue R = Repair	r <mark>S = Safety</mark> N	= Not Inspected
--	------------------------	---------------------------------	-----------------

7.6) Interior Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

7.7) Electrical Conditions



Appears Serviceable.

7.8) Lighting Conditions



Appears Serviceable.

7.9) Ceiling Fan Conditions



The ceiling fan(s) were operational at the time of the inspection. Mounting hardware of fans, light fixtures, and / or chandeliers was not visible or accessible for inspection. Appears Serviceable.

7.10) Smoke Detector Conditions



Could not reach

Appears Serviceable.

8 Dining room

Walls - Ceilings - Floors 8.1) Wall Conditions Appears Serviceable. 8.2) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. 8.3) Floor Conditions The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. 8.4) Heat Source Conditions 57.7 degrees **Windows - Doors** 8.5) Interior Window Conditions Appears Serviceable. 8.6) Interior Door Conditions The interior doors appeared to be in serviceable condition at the time of the inspection. **Electrical Conditions** 8.7) Electrical Conditions Appears Serviceable. 8.8) Lighting Conditions

9.6) Electrical Conditions

Appears Serviceable. Checked 3 accessible plugs

9 Living Room

Walls - Ceilings - Floors 9.1) Wall Conditions Appears Serviceable. 9.2) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. 9.3) Floor Conditions The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. 9.4) Heat Source Conditions 58.4 **Windows - Doors** 9.5) Interior Window Conditions Appears Serviceable. **Electrical Conditions**



9.7) Lighting Conditions



Appears Serviceable.

9.8) Ceiling Fan Conditions



Appears Serviceable.

Fireplace

Fireplace Location A fireplace is located at the living room.

Fireplace materials The fireplace is metal/pre-fabricated.

9.9) Fireplace Conditions

The fireplace is gas fired and was operable at the time of inspection. Client is advised to obtain information from the manufacturer regarding use, maintenance, and carbon monoxide risks if any. The general condition of the visible and accessible areas of the fireplace appeared to be in serviceable condition at the time of the inspection.

10 Primary Bedroom

Walls - Ceilings - Floors

10.1) Wall Conditions



Appears Serviceable.

10.2) Ceiling Conditions



There were stains at primary bedroom closet. The stain was dry at time of inspection. The inspector was unable to determine if the leak was active at the time of the inspectuon. Further evaluation by a qualified contractor is recommended. Please refer to limitations of inspection regarding mold / moisture related conditions.



Primary closet

10.3) Floor Conditions



Appears Serviceable.

10.4) Heat Source Conditions



Appears Serviceable.



Windows - Doors

10.5) Interior Window Conditions



The thermal pane window(s) at front side of house appear to have lost its / their thermal seal. Moisture, fogging, and hazing are common signs of this condition. While mostly cosmetic, this condition is generally not repairable. Correction would require replacement of the window(s) or window pane(s).



Cloudy window. Top sash has broken thermal pain

10.6) Interior Door Conditions



Pet related scratching / damage was observed at doors.



Apparent scratching

Electrical Conditions

10.7) Electrical Conditions



Appears Serviceable. (5) easily accessible plugs were tested

10.8) Lighting Conditions



Appears Serviceable.

10.9) Ceiling Fan Conditions



Appears Serviceable. Slight wobbling

10.10) Smoke Detector Conditions



Tested unit and smoke detector was operational at time of inspection

AS = Appears Serviceable | MI = Maintenance Issue | R = Repair | S = Safety | NI = Not Inspected



11 Upstairs Bedroom 1 (front of house)

Walls - Ceilings - Floors

11.1) Wall Conditions



Appears Serviceable.

11.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

11.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

11.4) Heat Source Conditions



Appears Serviceable. 58-59 degrees. Thermostat set to 73.



Windows - Doors

11.5) Interior Window Conditions



Some of the window screens were missing or not installed at time of inspection.

11.6) Interior Door Conditions



Appears Serviceable.

Electrical Conditions

11.7) Electrical Conditions



Appears Serviceable. 3 accessible plugs were tested and operational at time of inspection

11.8) Lighting Conditions



Appears Serviceable.

11.9) Smoke Detector Conditions



Appears Serviceable. Smoke detector was tested and responded to test at time of inspection.



Upstairs front bedroom 1

12 Upstairs Bedroom 2 (back of house)

Walls - Ceilings - Floors

12.1) Wall Conditions



Appears Serviceable.

12.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

12.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. Some staining was found on the carpets.

12.4) Heat Source Conditions



Appears Serviceable. Temperature 57-58 degrees. Thermostat set to 73



Windows - Doors

12.5) Interior Window Conditions



The sample of windows tested were operational at the time of the inspection.

12.6) Interior Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

12.7) Electrical Conditions



Appears Serviceable. 3 readily accessible outlets were tested and operational at time of inspection

12.8) Lighting Conditions



Appears Serviceable.

12.9) Ceiling Fan Conditions



Appears Serviceable.

12.10) Smoke Detector Conditions



Appears Serviceable.

13 Bonus Room 1 (upstairs Bedroom 3)

Walls - Ceilings - Floors 13.1) Wall Conditions Appears Serviceable. 13.2) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. 13.3) Floor Conditions The carpet has stains in a couple areas 13.4) Heat Source Conditions Appears Serviceable. Vents registered x degrees **Windows - Doors** 13.5) Interior Window Conditions Appears Serviceable. 13.6) Interior Door Conditions The interior doors appeared to be in serviceable condition at the time of the inspection. **Electrical Conditions** 13.7) Electrical Conditions Appears Serviceable. Testes x visible outlets 13.8) Lighting Conditions Appears Serviceable. 13.9) Ceiling Fan Conditions Appears Serviceable.

Appears Serviceable. Tested smoke detector, was operational at time of inspection

13.10) Smoke Detector Conditions

14 Bonus Room 2 (back of house with door leading to porch)

Walls - Ceilings - Floors 14.1) Wall Conditions Appears Serviceable. 14.2) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. 14.3) Floor Conditions The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. 14.4) Heat Source Conditions Appears Serviceable. **Windows - Doors** 14.5) Interior Window Conditions Appears Serviceable. 14.6) Interior Door Conditions The interior doors appeared to be in serviceable condition at the time of the inspection. **Electrical Conditions** 14.7) Electrical Conditions Appears Serviceable. Tested x number of outlets **14.8) Lighting Conditions** Appears Serviceable. 14.9) Ceiling Fan Conditions Appears Serviceable.

15 Kitchen

Walls - Ceilings - Floors

15.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.

15.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

15.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. There was one section of hardwood in the breakfast area that is slightly warped



Slight warping in the floor

15.4) Heat Source Conditions



Appears Serviceable. Vents registered 60 degrees, thermostat set to 73 degrees




Windows - Doors

15.5) Kitchen Window Conditions



Cracked glass pane(s) were observed at breakfast room top left window. There is a small chip in the window. Recommend repair as needed.



Chip in window.

15.6) Kitchen Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

15.7) Electrical Conditions



AS = Appears Serviceable | MI = Maintenance Issue | R = Repair | S = Safety | NI = Not Inspected 12 outlets tested. Appears Serviceable. 15.8) Lighting Conditions Appears Serviceable. Kitchen Sink - Counter tops - Cabinets 15.9) Counter Conditions Appears Serviceable. 15.10) Cabinet Conditions Appears Serviceable. 15.11) Sink Plumbing Conditions The kitchen sink appeared to be in serviceable condition at the time of the inspection. The faucet appeared to be in serviceable condition at the time of the inspection. The visible areas of the plumbing under the kitchen sink appeared to be in serviceable condition at the time of the inspection. 15.12) Garbage Disposal Condition The sink disposal was operable at the time of the inspection. Client should consult a licensed plumber, manufacturer, or disposal supply company for information on proper usage and safety related concerns. **Appliances** The range is gas. The oven is electric. Appears Stove - Range Type Serviceable.

15.13) Stove - Range Condition

Appears Serviceable.

15.14) Hood Fan Conditions

The hood light was in operational condition at the time of the inspection. Vent in middle of burners



Vent in middle of burners

15.15) Dishwasher Conditions



The dishwasher appeared to be in serviceable condition at the time of the inspection. This does not however guarantee future performance or conditions.

16 Primary Bathroom

Walls - Ceilings - Floors

16.1) Wall Conditions



Appears Serviceable.

16.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

16.3) Floor Conditions



Appears Serviceable.

16.4) Heat Source Conditions



Appears Serviceable. 61.7 degrees



Windows - Doors

16.5) Bathroom Window Conditions



Appears Serviceable.

16.6) Bathroom Door Conditions



Appears Serviceable.

Electrical Conditions

16.7) Electrical Conditions



Appears Serviceable. 3 readily available plugs testes

16.8) Lighting Conditions



Appears Serviceable.

16.9) Vent Fan Conditions



Appears Serviceable.

Bathroom Sink

16.10) Counter - Cabinet Conditions



Appears Serviceable.

16.11) Sink Conditions



The sink appeared to be in serviceable condition at the time of inspection in bath.


Shower - Tub - Toilet

16.12) Shower - Tub Conditions




The sunken tub has a leak when you fill the tub up to the top jet intakes and motor for "whirlpool" does not work.

the steam shower does not produce steam. Steam generator does not appear to work. In addition the steam shower has a leak as evident when inspecting the subfloor in the crawlspace.



Subfloor below steam shower is leaking



High moisture content in subflooring beneath steam shower

16.13) Toilet Conditions



The toilet appeared to be in serviceable condition at the time of inspection in bath.

17 Downstairs Bathroom

Walls - Ceilings - Floors

17.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.

17.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

17.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

17.4) Heat Source Conditions



Appears Serviceable. 66.2%



Windows - Doors

17.5) Bathroom Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

17.6) Electrical Conditions



GFIC (Ground Fault Interrupter Circuit) receptacle circuit (a safety device for outlets near water) recommended next to sink.



17.7) Lighting Conditions



Appears Serviceable.

17.8) Vent Fan Conditions



Appears Serviceable.

Bathroom Sink

17.9) Counter - Cabinet Conditions



Appears Serviceable.

17.10) Sink Conditions



The sink appeared to be in serviceable condition at the time of inspection in bath.

Shower - Tub - Toilet

17.11) Shower - Tub Conditions



The bathtub, faucet, and drains appeared to be in serviceable condition.

17.12) Toilet Conditions



The toilet appeared to be in serviceable condition at the time of inspection in bath.

18 Upstairs Bathroom

Walls - Ceilings - Floors 18.1) Wall Conditions The general condition of the walls appeared to be in serviceable condition at the time of the inspection. 18.2) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. **18.3) Floor Conditions** The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. 18.4) Heat Source Conditions Appears Serviceable. **Windows - Doors** 18.5) Bathroom Door Conditions The interior doors appeared to be in serviceable condition at the time of the inspection. **Electrical Conditions** 18.6) Electrical Conditions Appears Serviceable. 18.7) Lighting Conditions Appears Serviceable. 18.8) Vent Fan Conditions Appears Serviceable. **Bathroom Sink** 18.9) Counter - Cabinet Conditions

Appears Serviceable.

18.10) Sink Conditions



The sink appeared to be in serviceable condition at the time of inspection in bath.

Shower - Tub - Toilet

18.11) Shower - Tub Conditions



The bathtub, faucet, and drains appeared to be in serviceable condition.

18.12) Toilet Conditions



The toilet appeared to be in serviceable condition at the time of inspection in bath.

19 Garage - Laundry

Walls - Ceilings - Floors The garage is attached to the house. **Garage Type** 19.1) Siding Conditions (if detached) The visible and accessible portions of the exterior wall coverings appeared to be in serviceable condition at the time of the inspection. 19.2) Roof Conditions (if detached) Appears Serviceable. 19.3) Wall Conditions Appears Serviceable. 19.4) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection. 19.5) Floor Conditions The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. 19.6) Window Conditions Appears Serviceable. 19.7) Door Conditions

Moisture related damage was observed. Recommend further evaluation and repair as needed by a qualified / licensed contractor.



Man door casing shows some signs of water damage

19.8) Vehicle Door Conditions



Appears Serviceable.

19.9) Electrical Conditions



Appears Serviceable.

19.10) Lighting Conditions



Appears Serviceable.

Laundry Room

Location The laundry facilities are located in the laundry room.

19.11) Laundry Room Conditions



The visible and accessible portions of the laundry plumbing components appeared to be in serviceable condition at the time of inspection.

20 Foundation - Crawl Space

Foundation

Foundation Type

Crawl Space.



Foundation Material

Block.

20.1) Foundation Conditions



Appears Serviceable.

Flooring Structure

Flooring Support Type

The column / support is block columns. The wood framing floor system was constructed of 2 X 10 floor joists.

20.2) Flooring Support Conditions



The steam shower in the master bathroom appears to have a leak. The subfloor is wet. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.

AS = Appears Serviceable | MI = Maintenance Issue | R = Repair | S = Safety | NI = Not Inspected



